

Software Change 2.62

Fan Start Time delay extended to 2 minutes if necessary

GSM functionality in 3-6 fans fixed. Text would go out, but would not return status query.

New feature:

In the GSM options section, you can choose how many times the dryer will text the preprogrammed number in the event of a fault condition (2-10 times). Factory Default is still 10 times.

The Connection Error Page now also displays some possible fixes for your communication problem.