

Software Change 2.63

New System Diagnostics for PLC bus conditions

Final Dry ignores the air switch(s)

Refinements to Autobatch including previous batch fault recording.

Input MST sensor will only record data for control when BOTH paddle switches are made. Dryer assumes this to be a FULL condition.

Enhanced system fault analysis with input checking. Example: Load output (6A) is on, but load confirmation (47) is not and vice versa. This will help diagnose faulty hardware and or degradation to wiring integrity.